

Figure 5-3 Soft soil site flood impacts 100 year ARI event: Clarence River at Shark Creek / Maclean





Figure 5-4 Soft soil site flood impacts 20 year ARI event: Clarence River at Chatsworth and Harwood islands



I:\ENVA\Projects\EN028291\Technical\Spatial\Spatial_Directory\ArcGIS\Specialist_Reports\Phase2\Hydrological\W28_HYD_IMP_M_20y_LEW_r262.mxd